# UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

: 6,966,082 B2

Page 1 of 1

APPLICATION NO.: 10/700611

DATED

: November 22, 2005

**INVENTOR(S)** 

: Bloemer et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## Title page,

Item [73], Assignee, reads "... Westerkemp," and should read -- ... Westerkamp, --.

# Column 4,

Line 20, reads "...in a substantially vertically direction..." and should read -- ...in a substantially vertical direction... --.

#### Column 5.

Line 39, reads "...such as a an infant seat,..." and should read -- ...such as an infant seat,... --.

## Column 8,

Line 36, reads "...and lower arms 34F 34R, 34F', 34R' of..." and should read -- ...34F, 34R, 34F', 34R' of... --.

Line 60, reads "...first end 164a a cable 164." and should read -- ...first end 164a of cable 164. --.

# Column 9,

Lines 11-12, reads "A motor 190 positioned on a support surface 190,..." and should read -- A motor 188 positioned on a support surface 190,... --.

Signed and Sealed this

Eleventh Day of July, 2006

JON W. DUDAS Director of the United States Patent and Trademark Office